

Engineering Design - Project Management - Quality Consultants

PO Box 181 Lindfield, NSW 2070.

Tel : (612) 9882 2677 Fax: (612) 9882 2577 Web: www.MJCivil.com.au

Project Title: Concrete repair
5 Ronald Avenue, Harbord, NSW

Client : Mr Philip Johnson

STRUCTURAL CERTIFICATION

We hereby certify that the documented remedial measures for the rectification of Magnesite induced corrosion of concrete slab reinforcement, have been undertaken in full accord of current Australian standards and are in line with good working practise.

Referred Documentation

Structural Specification For Repair

Concrete Cracking & Spalling (magnesite attack)

Dated: October 2008

We also certify on the basis of periodic inspections undertaken by this office during the construction process, that the remediated structure conforms to the design intent of the referred documentation.

Certified by



Date:

26th October 2009